PRIVILEGED & CONFIDENTIAL COMMUNICATION IN ANTICIPATION OF LITIGATION

CITY OF CHICAGO

300000 C

EPA Region 5 Records Ctr.

222810

DEPARTMENT OF ENVIRONMENT **:OMPLAINT INVESTIGATION FORM**

222810		u
Received by Phone 311 =	Mail ☐ In Person ☐ Email ☐	Taken/Logged By:
Date Received:	_ Time: 11.06 Superviso	or Assigned:
DLPC #	County: COOK ESCODE:	
COMPLAINT LOCATION	050 W. armitage	<i>.</i>
FACILITY/COMPANY:	cent Plating work	PHONE:
CONFIDENTIAL COMPLAINAL Name: Address Phone:	Respond Facility: Address Phone:	
omplaint Details: Chemica	e Deeping thus	the walls into
reducent proper	ty.	
	<u> </u>	·
	····	
	INVESTIGATION SUMMARY	
By: P. BADILLO	Star #	Date: 4/27/07
Interviewed: 6. PRESIDENT		Time:
Findings:		
	STENARATIVE	
Conclusions:		
OUTICIDATOTIS.		
	——————————————————————————————————————	
		Closed
		00000 7/15/02-6160
Complainant notified of findings? Referred to:	Yes : No : Citation #	Court Date:

White • Investigator

City of Chicago Department of Environment NARRATIVE

Date: 6/27/02 Time: 1:45 P.M.

Site Address: 3650 W. ARMITAGE

Site Name: CRESCENT PLATING WORKS INC.

Investigator: P. BADILLO #09

Upon arrival I met with the owner, Mr. Emilio Valle of and he directed me into the basement of said property where I observed some apparent seepage through the wall from the adjacent plating company. I proceeded to take a PH of the liquid which appeared to be clear and it was 7 (neutral), however, there are black stains throughout the basement floor that is definitely related to the seepage. I was initially involved with this same situation 3-4 years ago and according to Mr. Valle, the seepage ceased for a while but has continued.

I visited the adjacent property, Cresc ant Plating Works located at 3650 W. Armitage and met with the president of the company, Mr. Paul Carr. He directed me to the east wall where I observed their barrel zinc plating line and where the alleged seepage is occurring. He claims they poured new concrete on the floor and repaired the muriatic tank/vat when we were initially involved back in 1998.

We proceeded to the basement. Mr. Carr witnessed the seepage and now believes it is perhaps due to a broken sewer tile underneath the floor of his property because there are three sewers that run parallel with the zinc plating line which is located on the east side of the building. He is going to immediately address this situation but needs a few days to contact his plumber to reroute the rinse discharge water from one sewer to another. I will follow up in a week.

Prescent Plating Works Inc.

CHICAGO, ILLINOIS 60647

OVER THE PHONE QUOTATIONS

PAUL CARR PRESIDENT

TEL 773/772-0110 FAX 773/772-7387 CRESCENT BANGUET

WALL

WALL

WALL

THE

COMMERCIAL

Not to Scale.
Al Boundaries are Approximate.



SITE SKETCH

CITY OF CHICAGO
DEPARTMENT OF ENVIRONMENT
FIELD OPERATIONS DIVISION

	6/27/02
DATE:	1.11 PM
TIME:	13150 W. AKN TAGE
SITE ADDRESS:	CRESCENT PLATINE
SITE CODE:	P. BADILLO
INSPECTOR:	COOK COUNTY, CHICAGO
COUNTY:	COOK COOK

CITY OF CHICAGO DEPARTMENT OF ENVIRONMENT PHOTOGRAPH SHEET

DATE: 6/27/02 TIME: 1: 45pm PHOTOGRAPHED BY: Pete Badello

